Stacking Power MOSFETs NMOS Configuration

By Kendrick De La Pena

Updated: 06/09/2014



Stacking MOSFETs – NMOS



Test 2

- NMOS Configuration
- MOSFET:
 - STP8NM60
- Calculated Capacitance Values:
 - 50pF, 100pF, 150pF, 200pF
- Max Voltage:
 - 2500 V
- Changes:
 - Replaced diodes with 10k Resistors

JGINEERING

 Used Cgs and Cgd values according to datasheet instead of behavior model

Test 2 – Calculations

Cgs	= 440 pF	Vd	= 500 V
Cgd	= 10 pF	Vgs	= 20 V
		Av	= 25

ELECTRICAL & COMPUTER ENGINEERING

To ensure the MOSFETs turn on, increase C2 to **50 pF**

Stacking MOSFETs – NMOS

Test 2 – Simulation & Values





Stacking MOSFETs – NMOS

Test 2 – Chip



- Use same board as Test 1 Chip
- As a result, axial lead resistors and a radial lead capacitor were used to fit the previous spots

JNIV ELECTRICAL & COMPUTER ENGINEERING

Stacking MOSFETs – NMOS

Test 2 – Setup





Stacking MOSFETs – NMOS

Test 2 – Sample 1 Results

- Vin = 500 V
- Switching = 400 V, or 80.0%
- Voltage Across (Difference):
 - M1: 465 V (-45)
 - M2: 343 V (-122)
 - M3: 236 V (-107)
 - M4: 140 V (-96)
 - M5: 49 V (-91)

ELECTRICAL &

- The waveform oscillates only from when switching to the high voltage
- The oscillation may be cause by the extra length from the lead resistors

APUTER ENGINEERING





CMOSedu.com

Stacking MOSFETs – NMOS

Test 2 – Sample 2 Results

- Vin = 752 V
- Switching = 560 V, or 74.5%
- Voltage Across (Difference):
 - M1: 700 V (-52)
 - M2: 515 V (-185)
 - M3: 356 V (-159)
 - M4: 216 V (-140)
 - M5: 82 V (-134)
- The results follow suit of the previous sample
- The initial difference between Vin and M1 are larger than the last test





Test 2 – Sample 3 Results

- Vin = 1.001 kV
- Switching = 660 V, 65.5%
- Voltage Across (Difference):
 - M1: 958 V (-43)
 - M2: 698 V (-260)
 - M3: 478 V (-220)
 - M4: 292 V (-186)
 - M5: 115 V (-177)

ELECTRICAL &

 As with the last test, the switching voltage got worse, but at a faster rate for this test

PUTER ENGINEERING





Test 2 – Conclusion

- Overall, resistors worked better than the diodes
- As mentioned, the additional length from the lead resistors caused a delay substantial enough to distort the wave
- The problem will be fixed by fabricating a new board with pads for resistors instead of diodes



Stacking MOSFETs – NMOS

